

www.ntake2.com

With an

n-take 2[®]

Alternate Intake for Combustible Air



PATENTED

This could have been prevented.



A blocked intake on dual pipe 90% furnace caused this No Heat situation



ASK YOUR DISTRIBUTOR FOR DETAILS